Quick Trimble Access 2101 Port Change

Only one thing needs to be changed…The port number.

Trimble Access/Settings/Connect/GNSS Contact…Edit your existing GNSS contact.

Change the IP Port from 8080 to 2101